

Studebaker SERVICE BULLETIN

APRIL

No. 310A



1956

SERVICE BULLETIN INDEX-No. 297, January, 1955, through No. 310, February, 1956

This Service Bulletin Index lists all the articles published in Studebaker Service Bulletins from Service Bulletin No. 297, January, 1955, through No. 310, February, 1956.

REFERENCE	BUL NO.	PAGE	MODEL	REFERENCE	BUL NO.	PAGE	MODEL
-A-				B-Cont'd.			
AIR CLEANER for trucks without AD gasket position	305 298	2 3	v8 Trucks Pres. & E38 Trucks	BRAKES-Cont'd. hydrovac brake booster lining (Raybestos) parking brake lever clip	305 307	3 2	E17, E38 E Series
neglect may affect performance	307	1		BREATHER TUBE FILTER PACK NOT USED ON V8	306 306	1 1	V8
AIR CONDITIONER - DES- SCRIPTION, OPERATION AND SERVICE	300	1	1955 Comm. & Pres.	-C-			
AIR CONDITIONING compressor shaft seal kits	308 307	2 2		CAB BODY MOUNTING	306	3	E Series Trucks
Novi directory	308	1		CAMSHAFTS FOR SERVICE	304	2	1951-1954 V8
AMMETER NEEDLE Fluctuation	308	1		CARBURETOR and jet sizes metering rod changes jet changes	299 299 298	7 2 10	1955 Comm. 1955 Pres. E Series Trucks
ANTI-FREEZE in new cars and trucks shipped from So. Bend in new cars and trucks shipped from So. Bend	302 308	1 2	1955 1956	CARPET FASTENING CHROME COATING - BUMPER BARS	297 297	5 3	1955 Pres.
ASBESTOS FIBRE TYPE CYLINDER HEAD GASKET	303	3	v8 Pass. car	CLIMATIZER INSTALLATION IN CARS WITH AIR CONDITIONING	305	1	Comm. & Pres.
AUTO-LITE WIPER HAS NO COVER	302	4		CLUTCH OPERATING ROD HOLE RELOCATED	305	3	E Series Trucks
AUTOMATIC CHOKE OPERATION 2-BARREL CARBURETOR	309 297	4 8	56B-56H E Series	CONNECTING ROD bearing inserts inserts - new heavy duty type	303 304	4 4	E28, E38 E28, E38
AXLE, FRONT				COOLING SYSTEM radiator drain cock sealer	310 309	6 1	2E Series Trucks
-B-				CRANKSHAFT BEARING CAP SCREW LOCKWIRE DISCON- TINUED	299	10	
BATTERY carrier change improvements	307 298	2 1	v8 Trucks				
BODY designations sealing	298 299	4 7	1955 Ultra-Vista				
BRAKES Bendix changes in hydrovac. master cylinder, and wheel cylinder	302 307	3 2	E5, E6, E7 E Series - 2 Ton Trucks				

REFERENCE	BUL. NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
C-Cont'd.				- F -			
CYLINDER HEAD				FLIGHTOMATIC TRANSMISSION			
cap screw torque specification change	305	8	V8	IN 56G CARS	310	3	56G
gasket - asbestos fibre type	303	3	18	drain plug and gasket assembly	310	3	Flightomatic
gasket improved	302	4	V8	FLOTO SCREEN RETAINING			
- D -				COTTER PIN	305	3	V8
DEFROSTER OPERATION	299	11		FONT END NOISE	304	4	1955
DELCO AUTO RADIO SERVICE	309	1	1956	FRONT SPRING SPACER			
DISTRIBUTOR REMOVAL ON				FOR SPEEDSTER	305	3	6HK7 Speedster
TRUCKS WITH V8 ENGINE				FEL PUMP MAY CAUSE			
AND CLIMATIZER	305	5	V8 Trucks	HARD STARTING	309	2	1955 Comm. & Pres.
DIRECTIONAL SIGNALS	298	6	E series	- G -			
DOME LIGHT REMOVAL	310	4	1956 Hawk Series	GASKETS RESTORED BY			
DOOR				SOAKING	299	10	
LOCK deflector interference with opening button	297	4	4 Door Models	GASKET SETS FOR AUTOMATIC DRIVE	299	11	AD
window glass replacement	309	1		GASOLINE			
- E -				gauge & heat indicator in cars and trucks shipped by rail	297	2	
ELECTRICAL SYSTEM				mileage chart	305	4	
equipment, 12-volt wiring rear harness	309	3	1956	GLASS BREAKAGE-LEFT DOOR	298	4	1955
	310	6	2E Series Trucks, 1/2 3/4 & 1 Ton	GOVERNOR WITH 2-Barrel CARBURETOR	308	3	E Series Trucks
ENGINE					303	4	E38
floto screen retaining cotter pin	305	3	V8	- H -			
gasket sets for all post-war models	303	1		HAND THROTTLE	310	6	V8 Trucks
heavy-duty trimetal bearings	307	1	V8	HEADLIGHTS - NEW SEALED BEAM	303	2	
oil leak at rear	308	2	V8	HEAVY DUTY TRIMETAL ENGINE BEARINGS FOR SERVICE	307	1	V8
oil overfilling is dangerous	302	2		HOOD INSULATION	297	3	1955
oil pan	409	4	2E5 Series Trucks	HRN - TONE	298	2	
rear main bearing oil seal revised - new installation procedure	306	3	V8	HUB AND DRUMS AVAILABLE SEPARATELY	305	4	1954-1955
replacement	306	4	2R, eR Series Trucks 1/2, 3/4 & 1 Ton	HYDROVAC			
				brake booster	305	3	E17, E38
replacement with 185 cu. in. for Champion	305	6	6G - 15G	changes in hydrovac, master cylinder, and wheel cylinder	307	2	E Series 2-Ton Truck
rocker arm oil return passages	-	4	1955-1956 V8	- I -			
EXHAUST SYSTEM INTERFERENCE - LEFT SIDE	303	3	V8	IGNITION			
				lock anti-rattle spring timing - V8 - advanced timing can cause difficulty	298	3	1955
					304	3	V8

REFERENCE	BUL. 10.	'AGE	MODEL	REFERENCE	BUL. NO.	'AGE	MODEL
-				- R -			
LETTER OF TRANSMITTAL MUST ACCOMPANY CLAIM FORMS	306	2		RADIATOR drain cock	310	6	2E Series Trucks
LUBRICANT FOR ROSS STEERING GEARS	299	2		repair claims upper tank reinforcing plate	297	2	
- M -					308	4	E Series Trucks
MOULDING CLIP REAR DOOR AND REAR QUARTER	298	2	Sedans	RADIO SERVICE (DELCO) RADIOS - TRUCKS	309	1	1956
				388	3		
- O -				REAR AXLE ratio change ratio option for E7 trucks - 3.73:1 ratios - President ring and pinion installation	299	2	1955 Comm.
OIL				299	12	E7	
level gage	304	2	E28, E38	299	1	1955 Pres.	
pressure relief valve spring heavier to prolong bearing life	302	4	E28, E38	305	4	1955 Champ	
pressure relief valve spring heavier	305	2	All Models Except E6, E11, 14, 16, 17	309	4	2E Series Trucks	
splash through filler tube	305	2	E series V8	shaft click noise	308	1	1955 Comm. & Pres.
OVERDRIVE TRANSMISSION WITHOUT REVERSE LOCKOUT SWITCH	298	7	OD	shaft nut torque speci- fication correction	309	2	1955 Comm. & Pres.
				REAR MAIN BEARING OIL SEAL REVISED - NEW INSTALLATION PROCEDURE	306	3	V8
- P -				303	3	1955 - W, F C, K and Y	
PAINT FINISH MAY BE DULL FROM WAXING	310	1		REAR QUARTER PANEL AND FENDER MOULDING UPPER PANEL	298	4	1955 F6
PAINT FORMULA				REFINISH PAINTED HEAD LAMP RIMS AND GRILLES	299	10	
1955 pass. cars	297	6		RCKER ARM OIL RETURN PASSAGES	309	4	1955-1956 V8
	304	1					
	305	1		- S -			
	306	2		SALT DAMAGE TO FINISH	299	1	
1956 pass. cars	310	2 3		SEALING FRONT BODY SECTION ON ULTRA-VISTA MODELS	299	7	1955 Sedan and Statio wagon
2E Series trucks	310	7					
PARKING BRAKE LEVER CLIP	306	1	1954-1955	SEAT BACK RATTLE	304	2	E Series
PHILCO RADIO SERVICE STATION DIRECTORY	299	10		SPEEDOMETER DRIVE GEAR	298	2	1955 Pres. r//AD
PISTON FITTING CLEARANCE	297	3	V8				
PISTON PIN LOCK SCREW LOCK WASHER TYPE CHANGED	299	12	V8	SPEEDSTER SERVICE INFORMATION			
POWER BRAKE ADJUSTMENT	299	9	1955	ammeter	301	3	Speedster
POWER SEAT ADJUSTER STICKING	302	3		clock	301	3	Speedster
POWER STEERING PUMP BRACKET FAILURE	304	2	V8	front spring spacer	305	3	Speedster
POWER TAKE-OFF MODELS	310	5	Trucks W/T98A Transmission	gas gage	301	3	Speedster
				instrument board cover	301	4	Speedster
				mouldings	301	5	Speedster
				oil pressure gage	301	3	Speedster

REFERENCE	BUL NO.	PAG	MODEL	REFERENCE	BUL NO.	PAG	MODEL
S-Cont'd.				T-Cont'd.			
SPEEDSTER SERVICE-Cont'd				TRANSMISSION-CONT'D.			
radio	301	4	Speedster	4-speed synchromesh	310	4	2E Series Trucks
speedometer	301	4	Speedster	5-speed overdrive	297	7	E28, E38
tachometer	301	2	Speedster	TRUCKS - E SERIES			
temperature gage	301	3	Speedster	SERVICE INFORMATION	297	1	E Series
SQUEAK ELIMINATION,				TRUCKS WIRED FOR			
FENDER-TO-COWL CONTACT	298	10	1953-195s	DIRECTIONAL SIGNALS	298	6	E series
STARTING SERIALS	298	2	1955	TRUNK LID LATCH	309	3	1956 Sedan:
STEERING GEAR LUBRICANT	299	2	For Ross Gear	TUBELESS TIRES ON TRUCKS	305	2	1/2 Ton Trucks
SUN VISOR NOISE	297	6	Sedans and Stat. wagon:	TWO-SPEED REAR AXLE SHIFT ASSEMBLY	309	4	2E Series Trucks
- T -				-U-			
TIMING MARK ON VIBRATION DAMPER	310	6	2E7, 2E12	UNIVERSAL JOINT flange torque limits -			
TIRE PRESSURES IMPORTANT FOR SAFETY	310	1		5-speed transmission	302	4	2E38
TIRE VALVE EXTENSION	306	1		u-bolt torque specification change	299	10	
TOOL FOR ROUND SIC-SLOTTED NUTS	304	4	5-speed Trans.				
TORQUE CONVERTER				-V-			
1950 Commander converter-to-drive plate indexing	298	6	1950 Comm.	VALVE			
housing screen no longer used	304	1	17A	clearance specific			
housing stud nuts	299	2	1955	cations	297	3	V8
part numbers	305	2	AD	lifter bore reamer	297	5	18
valve body changes	298	2	1950-1955	lifters in over sizes	299	6	V8
TRANSMISSION	298	1	1955	lifters - use correct type	299	7	18
automatic drive				VIBRATION DAMPER INCORRECTLY MARKED	310	6	2E7, 2E12 Trucks
changes for 1955	298	3	1955				
fluid level checking	302	1		- W -			
gasket sets	299	11		WAX MAY DULL NEW CAR FINISH	310	1	
low and forward brake cylinder plate	310	1		WEATHER SEALS, HARDTOP DOOR FRONT	297	4	HT
multiple disc clutch parts	298	6		WEATHER STRIP SHIM FOR FRONT DOORS	305	1	Sedans and Stat. Wagons
oil seal kit	309	2		WINDOW GLASS REPLACEMENT - DOOR	309	1	
rap with high speed no-load operation	306	2		WINDSHIELD WIPER KNOB PULLS OFF	299	11	Ultra-Vista Sedans and Stat. Wagons
reverse engagement slow	302	2		WIRING REAR HARNESS	410	6	2E Trucks
valve block	299	12	1955				1/2, 3/4, 1 Ton
whistle in Comm. and Pres.	306	1	1955				
flightomatic in 56G cars	310	3	56G				
flightomatic drain plug and gasket assembly	310	3	FLIGHTOMATIC				
overdrive without reverse lockout switch	298	7	OD				
remote control	298	1	1955				

STUDEBAKER DIVISION
STUDEBAKER-PACKARD CORP.
SOUTH BEND 27, INDIANA